Series 719, LF719

Double Check Valve Assemblies

Sizes 1/2" - 2"

Repair Kits

When ordering specify Ordering Code, Kit No., and Valve Size.

	ORDERING CODE	KIT NO.	SIZE	LIST PRICE
	Total Rep	air Kits		
*	0889083	RK 719-T	1/2"	\$67.75
Ë	0889084	RK 719-T	3/4"	98.00
<u>п</u>	0889085	RK 719-T	1"	102.00
₫	0889086	RK 719-T	1 1/4" - 1 1/2"	188.00
ы	0889087	RK 719-T	2"	192.00

Kit consists of: 2 first or second check repair kits

1st or 2nd Check Kits

in	0888100	RK 719R10 CK4	1/2" - 3/4"	46.00
Ш	0889060	RK 719 CK4	1/2"	37.75
Ë	0889061	RK 719 CK4	3/4"	54.50
Δ	0889062	RK 719 CK4	1"	56.50
	0888101	RK 719 CK4	1 1/4" – 1 1/2"	104.50
	0888102	RK 719 CK4	2"	107.00

Kit consists of: disc holder, spring and cover 0-ring.

1st or 2nd Check Rubber Parts Kits

Ĭш	0888103	RK 719R10 RC4	1/2" - 3/4"	14.50
	0889063	RK 719 RC4	1/2"	11.25
Ë	0889064	RK 719 RC4	3/4"	11.25
۵	0889065	RK 719 RC4	1"	11.25
	0888104	RK 719 RC4	1 1/4" – 1 1/2"	14.75
	0888105	RK 719 RC4	2"	15.50

Kit consists of: disc rubber, seat 0-ring and cover 0-ring.

1st or 2nd Check Seat Kits

iш	0888997	RK 719R10 S	1/2" - 3/4"	32.25
I III	0889069	RK 719 S	1/2"	29.00
ü	0889070	RK 719 S	3/4"	38.25
	0889071	RK 719 S	1"	39.50
	0888998	RK 719 S	1 1/4" – 1 1/2"	60.25
	0888999	RK 719 S	2"	66.75

Kit consists of: seat, seat 0-ring and cover 0-ring.

Complete Valve Rubber Parts Kits

ш	0889078	RK 719 RT	1/2"	45.75
#	0889079	RK 719 RT	3/4"	47.50
Ш	0889080	RK 719 RT	1"	57.50
₫	0889081	RK 719 RT	1 1/4" – 1 1/2"	61.00
۳	0889082	RK 719 RT	2"	62.00


Kit consists of: 2 check seat 0-rings, 2 check cover 0-rings, 2 check rubbers.

1st or 2nd Check Cover Kits

		a chook cover the		
:	0889072	LFRK 719-R10-C	1/2" - 3/4"	77.00
	0794039	LFRK 719 C	1/2"	58.75
888	0794040	LFRK 719 C	3/4"	95.00
9	0794041	LFRK 719 C	1"	98.75
ď	0794042	LFRK 719 C	1 1/4" – 1 1/2"	130.50
	0794043	LFRK 719 C	2"	153.00

Kit consists of: cover and cover 0-ring.

For 1 1/4" 719R15 models use 1 1/4" - 1 1/2" repair kits.



^{*}The wetted surface of this product contacted by consumable water contains less than 0.25% of lead by weight.